

26 January 2018

POLLOCK & SONS CRANE HIRE LIMITED
wayne@pollockcranes.co.nz

Dear customer,

We've calculated your proposed operator rating for the period of 01/01/2016 to 31/12/2017.

Transport service licence (TSL) name: **POLLOCK & SONS CRANE HIRE LIMITED**
TSL number: **0240459**
Your proposed rating: **4 stars**
Your overall score: **0.7977**

We'd like to let you know that:

- **this proposed rating is for your information only and will not be published**
- this proposed rating has been calculated in accordance with Land Transport Rule: Operator Safety Rating 2008
- this proposed rating may be updated as a result of the operator rating system (ORS) errors and omissions process
- your final rating will be recalculated after the errors and omissions process has been completed, and will be reconfirmed to you **only** if it has changed
- this information may be used to inform NZ Transport Agency, Accident Compensation Corporation (ACC) and NZ Police advisory and enforcement activity but will not be shared publicly, unless required by law.

What does the rating mean?

Operator safety ratings indicate an operator's level of compliance with land transport safety legislation, and therefore their safety risk, based on the results of safety events. Events included in ORS are certificate of fitness (CoF) inspections, roadside inspections and certain types of offending.

Here are the possible ratings:

Rating	Description	Overall score range
5 stars	Very good level of compliance	0 - 0.4999
4 stars	Good level of compliance	0.5000 - 2.1041
3 stars	Unsatisfactory level of compliance	2.1042 - 3.7082
2 stars	Very unsatisfactory level of compliance	3.7083 - 5.3124
1 star	Extremely unsatisfactory level of compliance	5.3125 or higher

Changes for passenger service operators

On 1 October 2017, passenger service licences (PSLs) became invalid and were replaced with small passenger service licences (SPSLs) and large passenger service licences (LPSLs). If you held a PSL before 1 October 2017, we've transferred your ORS history across to your new LPSL record. This will keep your rating continuous and consistent. You can find more information about SPSLs and LPSLs at www.nzta.govt.nz/commercial-driving/transport-service-licences.

Update to the categorisation of defects

We've made some changes to the categorisation of defects (CoD), which came into effect on **1 July 2016**. The changes include new codes and descriptions, which are now in use for vehicles that have been inspected from 1 July 2016.

You can find more information about the new CoD on our website at www.nzta.govt.nz/commercial-driving/operator-rating-system-ors. The old CoD information stopped being used at midnight on 30 June 2016, but will remain available online for the next couple of years so you can refer to it for infringements using the old CoD information.

IMPORTANT NOTE FOR OPERATORS

Operator safety ratings are an indication of general compliance with land transport legislation. A positive rating (eg good, or very good) is not a guarantee of compliance with all land transport legislation. Where the NZ Transport Agency suspects an operator is in breach of land transport legislation, we will investigate and enforce the breach in accordance with the relevant legislation. A positive rating will not be accepted by the NZ Transport Agency as proof that the suspected breach is unsubstantiated.

What if I find an error?

If you believe your proposed rating includes information that's incorrect, events have been omitted, or you wish to contest an event you can apply via the errors and omissions process.

If you wish to apply to the errors and omissions process, please do so within 20 working days of receiving this letter. You'll need to supply supporting documents, such as:

- an unaltered copy of the CoF or roadside inspection checksheet (CVIR form)
- a copy of any documents showing the vehicle was owned by another operator at the time of the event
- a copy of any lease agreement showing the vehicle was leased to another operator at the time of the event.

You can email your application to ors@nzta.govt.nz or post it to ORS Errors and Omissions, Freight & Register Records Team, NZ Transport Agency, Private Bag 11777, Palmerston North 4442.

If you're satisfied that your proposed rating is correct you don't need to do anything further.

Information about the ORS, how safety event information is collected and how the ratings are calculated is available on our website at www.nzta.govt.nz/commercial-driving/operator-rating-system-ors.

Do we have your correct email address?

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

If you have any questions regarding the ORS process or how to improve your safety compliance, please call us on 0800 699 000, Monday to Friday 8am to 6pm, or email us at ors@nzta.govt.nz.

Yours sincerely



Riccardo Areosa
Customer Assessments
NZ Transport Agency

Proposed rating summary

TSL name: **POLLOCK & SONS CRANE HIRE LIMITED**
 TSL number: **0240459**
 Rating period: **01/01/2016 to 31/12/2017**
 Proposed rating: **4 stars**
 Overall score: **0.7977**

Certificate of fitness inspections

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
14/01/2016	VTNZ MALEME STREET - TAURANGA	B472D	PASS		
18/01/2016	VTNZ MALEME STREET - TAURANGA	A1022	FAIL	Mudguards Cracked L/R	2
				Service Brake To improve Rr	5
				Deck/Load Anchrgs Cracked Fr	4
				Deck/Load Anchrgs Corrosion All	4
19/01/2016	VTNZ MALEME STREET - TAURANGA	BUN335	PASS		
26/01/2016	VTNZ MALEME STREET - TAURANGA	FSE373	PASS		
04/02/2016	VTNZ SYLVIA PARK	T915R	PASS		
10/02/2016	VTNZ MALEME STREET - TAURANGA	370A	PASS		
10/02/2016	VTNZ MALEME STREET - TAURANGA	371A	PASS		
10/02/2016	VTNZ MALEME STREET - TAURANGA	EWT126	PASS		
18/02/2016	VTNZ MALEME STREET - TAURANGA	T704C	PASS		
02/03/2016	VTNZ SYLVIA PARK	I4072	PASS		
03/03/2016	VTNZ MALEME STREET - TAURANGA	S6321	PASS		
03/03/2016	VTNZ MALEME STREET - TAURANGA	S6322	PASS		
31/03/2016	VTNZ MALEME STREET - TAURANGA	ENJ363	PASS		
05/04/2016	VTNZ MALEME STREET - TAURANGA	C2009	PASS		
05/04/2016	VTNZ MALEME STREET - TAURANGA	CFR505	PASS		
11/04/2016	VTNZ TE RAPA	CZR714	PASS		
11/04/2016	VTNZ TE RAPA	T8185	PASS		
13/04/2016	VTNZ MALEME STREET - TAURANGA	CWE786	PASS		
19/04/2016	VTNZ MALEME STREET - TAURANGA	EYG393	PASS		
20/04/2016	VTNZ MALEME STREET - TAURANGA	2360M	FAIL	Slack Adjusters To improve All	5
				Slack Adjusters To operate Fr	5
20/04/2016	VTNZ MALEME STREET - TAURANGA	2360M	PASS		
20/04/2016	VTNZ MALEME STREET - TAURANGA	DCG135	PASS		
22/04/2016	VTNZ SYLVIA PARK	WU6934	PASS		
29/04/2016	VTNZ MALEME STREET - TAURANGA	B438Z	PASS		
04/05/2016	VTNZ KEREITI ST - MT MAUNGANUI	FYH493	PASS		
05/05/2016	VTNZ MALEME STREET - TAURANGA	T6906	PASS		

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
05/05/2016	VTNZ MALEME STREET - TAURANGA	T6907	PASS		
05/05/2016	VTNZ MALEME STREET - TAURANGA	W596T	PASS		
13/05/2016	VTNZ MALEME STREET - TAURANGA	CDK502	PASS		
13/05/2016	VTNZ MALEME STREET - TAURANGA	REXZ2	PASS		
16/05/2016	VTNZ MALEME STREET - TAURANGA	ESJ816	PASS		
19/05/2016	VTNZ WIRI	7664C	PASS		
19/05/2016	VTNZ WIRI	O3714	PASS		
19/05/2016	VTNZ WIRI	O3715	PASS		
20/05/2016	VTNZ KEREITI ST - MT MAUNGANUI	U2024	PASS		
27/05/2016	VTNZ SYLVIA PARK	6855I	PASS		
01/06/2016	VTNZ KEREITI ST - MT MAUNGANUI	TOMMOZ	PASS		
11/06/2016	VTNZ MALEME STREET - TAURANGA	U766A	PASS		
11/06/2016	VTNZ MALEME STREET - TAURANGA	U767A	PASS		
13/06/2016	VTNZ MALEME STREET - TAURANGA	R436Y	PASS		
23/06/2016	VTNZ MALEME STREET - TAURANGA	W6505	PASS		
23/06/2016	VTNZ MALEME STREET - TAURANGA	W6506	PASS		
13/07/2016	VTNZ MALEME STREET - TAURANGA	FSE373	PASS		
27/07/2016	VTNZ MALEME STREET - TAURANGA	BUN335	PASS		
01/08/2016	VTNZ MALEME STREET - TAURANGA	B472D	PASS		
16/08/2016	VTNZ MALEME STREET - TAURANGA	T915R	PASS		
24/08/2016	VTNZ MALEME STREET - TAURANGA	I4072	PASS		
30/08/2016	VTNZ SYLVIA PARK	S6321	PASS		
31/08/2016	VTNZ MALEME STREET - TAURANGA	T704C	PASS		
31/08/2016	VTNZ SYLVIA PARK	EWT126	PASS		
05/09/2016	VTNZ SYLVIA PARK	S6322	PASS		
19/09/2016	VTNZ MALEME STREET - TAURANGA	370A	PASS		
19/09/2016	VTNZ MALEME STREET - TAURANGA	371A	FAIL	Structure Corrosion Rr	3
03/10/2016	VTNZ MALEME STREET - TAURANGA	371A	PASS		
05/10/2016	VTNZ SYLVIA PARK	C2009	PASS		
12/10/2016	VTNZ WIRI	ENJ363	PASS		
17/10/2016	VTNZ MALEME STREET - TAURANGA	CFR505	PASS		
17/10/2016	VTNZ MALEME STREET - TAURANGA	CWE786	PASS		
19/10/2016	VTNZ TE RAPA	CZR714	PASS		
19/10/2016	VTNZ TE RAPA	T8185	PASS		
21/10/2016	VTNZ TE RAPA	EYG393	PASS		
28/10/2016	VTNZ MALEME STREET - TAURANGA	B438Z	PASS		
28/10/2016	VTNZ MALEME STREET - TAURANGA	DCG135	PASS		
01/11/2016	VTNZ KEREITI ST - MT MAUNGANUI	2360M	PASS		

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
01/11/2016	VTNZ MALEME STREET - TAURANGA	W596T	PASS		
02/11/2016	VTNZ MALEME STREET - TAURANGA	FYH493	PASS		
02/11/2016	VTNZ MALEME STREET - TAURANGA	U2024	PASS		
07/11/2016	VTNZ MALEME STREET - TAURANGA	ESJ816	PASS		
09/11/2016	VTNZ MALEME STREET - TAURANGA	EYW326	PASS		
09/11/2016	VTNZ MALEME STREET - TAURANGA	REXZ2	PASS		
14/11/2016	VTNZ MALEME STREET - TAURANGA	U766A	PASS		
14/11/2016	VTNZ MALEME STREET - TAURANGA	U767A	PASS		
16/11/2016	VTNZ MALEME STREET - TAURANGA	CDK502	PASS		
16/11/2016	VTNZ MALEME STREET - TAURANGA	T6906	PASS		
16/11/2016	VTNZ MALEME STREET - TAURANGA	T6907	PASS		
18/11/2016	VTNZ MALEME STREET - TAURANGA	7664C	PASS		
18/11/2016	VTNZ MALEME STREET - TAURANGA	WU6934	PASS		
22/11/2016	VTNZ MALEME STREET - TAURANGA	6855I	PASS		
25/11/2016	VTNZ KEREITI ST - MT MAUNGANUI	TOMMOZ	PASS		
02/12/2016	VTNZ MALEME STREET - TAURANGA	M738R	PASS		
07/12/2016	VTNZ TE RAPA	P603C	PASS		
12/12/2016	VTNZ MALEME STREET - TAURANGA	O3714	PASS		
12/12/2016	VTNZ MALEME STREET - TAURANGA	O3715	PASS		
09/01/2017	VTNZ SYLVIA PARK	R436Y	PASS		
12/01/2017	VTNZ MALEME STREET - TAURANGA	W6505	PASS		
12/01/2017	VTNZ MALEME STREET - TAURANGA	W6506	PASS		
31/01/2017	VTNZ MALEME STREET - TAURANGA	C2009	FAIL	Service Brake To improve Rr	5
31/01/2017	VTNZ MALEME STREET - TAURANGA	EDE767	PASS		
01/02/2017	VTNZ MALEME STREET - TAURANGA	C2009	PASS		
03/02/2017	VTNZ TE RAPA	T915R	PASS		
08/02/2017	VTNZ MALEME STREET - TAURANGA	B472D	PASS		
13/02/2017	VTNZ MALEME STREET - TAURANGA	FSE373	PASS		
17/02/2017	VTNZ MALEME STREET - TAURANGA	BUN335	PASS		
24/02/2017	VTNZ SYLVIA PARK	EWT126	PASS		
06/03/2017	VTNZ MALEME STREET - TAURANGA	T704C	PASS		
10/03/2017	VTNZ MALEME STREET - TAURANGA	S6321	PASS		
10/03/2017	VTNZ MALEME STREET - TAURANGA	S6322	PASS		
17/03/2017	VTNZ MALEME STREET - TAURANGA	370A	FAIL	Service Brake Match Rr	5
17/03/2017	VTNZ MALEME STREET - TAURANGA	370A	PASS		
17/03/2017	VTNZ MALEME STREET - TAURANGA	371A	PASS		
13/04/2017	VTNZ MALEME STREET - TAURANGA	CWE786	PASS		
18/04/2017	VTNZ KEREITI ST - MT MAUNGANUI	CFR505	PASS		

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
22/04/2017	VTNZ KEREITI ST - MT MAUNGANUI	EYG393	PASS		
24/04/2017	VTNZ MALEME STREET - TAURANGA	ENJ363	PASS		
27/04/2017	VTNZ - PERFORMANCE DIESELS LIMITED	FYH493	PASS		
03/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	236ØM	PASS		
03/05/2017	VTNZ TE RAPA	CZR714	PASS		
03/05/2017	VTNZ TE RAPA	T8185	PASS		
05/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	W596T	PASS		
12/05/2017	VTNZ TE RAPA	REXZ2	PASS		
15/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	B438Z	PASS		
15/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	DCG135	PASS		
19/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	ESJ816	PASS		
19/05/2017	VTNZ SYLVIA PARK	EYW326	PASS		
19/05/2017	VTNZ TE RAPA	CDK5Ø2	PASS		
19/05/2017	VTNZ TE RAPA	T69Ø6	PASS		
19/05/2017	VTNZ TE RAPA	T69Ø7	PASS		
24/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	U2Ø24	PASS		
27/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	7664C	PASS		
31/05/2017	VTNZ KEREITI ST - MT MAUNGANUI	6855I	PASS		
02/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	M738R	PASS		
02/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	P6Ø3C	PASS		
06/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	TOMMOZ	PASS		
07/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	WU6934	PASS		
12/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	U766A	PASS		
12/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	U767A	PASS		
21/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	O3714	PASS		
21/06/2017	VTNZ KEREITI ST - MT MAUNGANUI	O3715	PASS		
10/07/2017	VTNZ KEREITI ST - MT MAUNGANUI	R436Y	PASS		
13/07/2017	VTNZ KEREITI ST - MT MAUNGANUI	I4Ø72	PASS		
14/07/2017	VTNZ KEREITI ST - MT MAUNGANUI	W65Ø5	PASS		
14/07/2017	VTNZ KEREITI ST - MT MAUNGANUI	W65Ø6	PASS		
27/07/2017	VTNZ KEREITI ST - MT MAUNGANUI	K477C	PASS		
11/08/2017	VTNZ SYLVIA PARK	C2ØØ9	PASS		
11/08/2017	VTNZ SYLVIA PARK	EDE767	PASS		
14/08/2017	VTNZ KEREITI ST - MT MAUNGANUI	B472D	PASS		
15/08/2017	VTNZ - PERFORMANCE DIESELS LIMITED	FSE373	PASS		
17/08/2017	VTNZ KEREITI ST - MT MAUNGANUI	BUN335	PASS		
21/08/2017	VTNZ KEREITI ST - MT MAUNGANUI	T915R	PASS		
24/08/2017	VTNZ SYLVIA PARK	EWT126	PASS		

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
11/09/2017	VTNZ SYLVIA PARK	37ØA	PASS		
14/09/2017	VTNZ SYLVIA PARK	S6321	PASS		
14/09/2017	VTNZ SYLVIA PARK	S6322	PASS		
12/10/2017	VTNZ - PERFORMANCE DIESELS LIMITED	T7Ø4C	PASS		
17/10/2017	VTNZ KEREITI ST - MT MAUNGANUI	CWE786	PASS		
24/10/2017	VTNZ KEREITI ST - MT MAUNGANUI	CFR5Ø5	PASS		
26/10/2017	VTNZ KEREITI ST - MT MAUNGANUI	EYG393	PASS		
31/10/2017	VTNZ KEREITI ST - MT MAUNGANUI	ENJ363	PASS		
01/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	REXZ2	PASS		
07/11/2017	VTNZ - PERFORMANCE DIESELS LIMITED	FYH493	PASS		
08/11/2017	VTNZ - PERFORMANCE DIESELS LIMITED	7664C	PASS		
08/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	W596T	PASS		
09/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	236ØM	PASS		
10/11/2017	VTNZ TE RAPA	CZR714	PASS		
10/11/2017	VTNZ TE RAPA	T8185	PASS		
15/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	H6957	PASS		
17/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	DCG135	PASS		
17/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	EYW326	PASS		
20/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	B438Z	PASS		
20/11/2017	VTNZ SYLVIA PARK	CDK5Ø2	PASS		
20/11/2017	VTNZ SYLVIA PARK	T69Ø6	PASS		
20/11/2017	VTNZ SYLVIA PARK	T69Ø7	PASS		
22/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	ESJ816	PASS		
28/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	U2Ø24	PASS		
30/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	M738R	PASS		
30/11/2017	VTNZ KEREITI ST - MT MAUNGANUI	P6Ø3C	PASS		
07/12/2017	VTNZ KEREITI ST - MT MAUNGANUI	6855I	PASS		
08/12/2017	NORTH CANTERBURY TRUCK AND TRACTOR SERVICES LIMITED	U766A	PASS		
08/12/2017	NORTH CANTERBURY TRUCK AND TRACTOR SERVICES LIMITED	U767A	PASS		
08/12/2017	VTNZ KEREITI ST - MT MAUNGANUI	TOMMOZ	PASS		
21/12/2017	VTNZ SYLVIA PARK	O3714	PASS		
21/12/2017	VTNZ SYLVIA PARK	O3715	PASS		

Roadside inspections

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
07/01/2016	ROKAWA	FYH493	PASS		

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

Inspection date	Inspection location	Vehicle plate	Result	Fault description	Score
07/01/2016	ROKAWA	T704C	PASS		
10/02/2016	ROKAWA	ESJ816	FAIL	Only 1 required rear reflector fitted	5
17/03/2016	PAENGAROA	DCG135	PASS		
09/05/2016	KARAPIRO	T915R	PASS		
09/05/2016	KARAPIRO	TOMMOZ	PASS		
23/05/2016	GISBORNE	B472D	PASS		
23/05/2016	GISBORNE	BUN335	FAIL	Fluid leaks other	1
18/07/2016	WAIKATO	2360M	PASS		
18/07/2016	WAIKATO	CWE786	PASS		
20/07/2016	CAMBRIDGE	CDK502	PASS		
20/07/2016	CAMBRIDGE	T6906	PASS		
03/09/2016	PAENGAROA	DCG135	FAIL	Cab roof lamp not operational, not securely fitted, damaged, obscured, emits colour other than amber	1
12/12/2016	ROKAWA	DCG135	FAIL	One or more front park lamps not operational (anytime)	1
13/02/2017	TATUANUI	FYH493	PASS		
13/02/2017	TATUANUI	T6906	PASS		
13/02/2017	TATUANUI	T6907	PASS		
25/02/2017	NGATEA	EYG393	PASS		
25/02/2017	NGATEA	T6906	PASS		
25/02/2017	NGATEA	T6907	PASS		
28/02/2017	PIKOWAI	FYH493	PASS		
28/02/2017	PIKOWAI	T6906	PASS		
28/02/2017	PIKOWAI	T6907	FAIL	Tread insufficient, any other tyres <input checked="" type="checkbox"/> not operated in rain	5
04/05/2017	PAENGAROA	ESJ816	FAIL	One direction Indicator lamp not working	1
09/06/2017	TIKITERE	B438Z	PASS		
09/06/2017	TIKITERE	DCG135	PASS		
17/07/2017	TE POI PITS (SH29)	370A	PASS		
17/07/2017	TE POI PITS (SH29)	371A	PASS		
17/07/2017	TE POI PITS (SH29)	TOMMOZ	PASS		
28/09/2017	OHAKA	FYH493	PASS		
28/09/2017	OHAKA	K477C	FAIL	Fluid leaks other	1
29/09/2017	NORMANBY	FYH493	PASS		
29/09/2017	NORMANBY	K477C	PASS		
30/10/2017	PUKETE	B472D	PASS		
30/10/2017	PUKETE	BUN335	PASS		

If you'd like to update your email address, please send your name, TSL number and new email address to ors@nzta.govt.nz.

Traffic / infringement offence information

Offence date	Offence location	Vehicle plate	Driver/operator	Conviction date	Description	Score
04/03/2016	STATE HIGHWAY 2/NETHERTON	CZR714	PETER MARK STORRY	28/05/2016	Driver or Passenger not wearing seat belt	50
23/05/2016	BACK ORMOND ROAD/GISBORNE	BUN335	JOHN CLAUDE FOSTER	01/06/2016	Exceeded 90 km/h with heavy motor vehicle	60
15/07/2016	GREAT SOUTH ROAD/HUNTLY	EYG393	PETER DOUGLAS HINTON	22/07/2016	Exceeded 70 km/h posted speed limit	60
23/09/2016	TAKITIMU DRIVE/TAURANGA	ESJ816	DANIEL GEORGE O'SULLIVAN	28/12/2016	Driver or Passenger not wearing seat belt	50
28/02/2017	SH 2/PIKOWAI	FYH493	MARK ALLEN RUSH	19/05/2017	Exceeded 90 km/h with heavy motor vehicle	60
09/06/2017	TE NGAE ROAD/ROKAWA	B438Z	POLLOCK & SONS CRANE HIRE LIMITED	26/06/2017	OD vehicle breached requirements	20
30/10/2017	MAUI STREET/PUKETE	BUN335	BRADLEY STEVEN WELSH	29/12/2017	Driver or Passenger not wearing seat belt	50

Crash incident information (not included in rating)

No event information recorded.